

**Loading status of 132 kV/220 kV/400 kV Transmission Works (for 3<sup>rd</sup> Quarter - Year 2016-17)**

**Sub-stations**

<b>Sr. No.</b>	<b>Name of the Sub-station</b>	<b>% Loading (As recorded during 3<sup>rd</sup> quarter for the Year 2016-17)</b>	<b>Remedial measures taken by PSTCL for de- loading of Power T/F</b>
No overloading was recorded on any power transformer of any voltage ratio.			

**Transmission Lines**

<b>Sr. No.</b>	<b>Name of the Transmission line</b>	<b>% Loading (As recorded during 3<sup>rd</sup> quarter for the Year 2016-17)</b>	<b>Remedial measures taken by PSTCL for de- loading of Transmission Line</b>
No overloading was recorded on any 132 kV/220 kV/400 kV transmission line.			